

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

September 12, 2006

Ken Madsen, Administrator Fairwinds - Sandcreek 3310 Valencia Dr Idaho Falls, ID 83404

License #: RC-661

Dear Mr. Madsen:

On July 27, 2006, a survey was conducted at Fairwinds - Sandcreek. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Mark Grimes, Health Facility Surveyor, Residential Community Care Program, at (208) 334-6626.

Sincerely,

MARK GRIMES

Team Leader

Health Facility Surveyor

Facility Fire, Life Safety, and Construction Program

MG/slc

c:

Mark Grimes, Supervisor, Facility Fire, Life Safety, and Construction Program



JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0326 PHONE: (208) 334-6262 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

August 9, 2006

Ken Madsen, Administrator Fairwinds - Sandcreek 3310 Valencia Dr Idaho Falls, ID 83404

Dear Mr. Madsen:

On July 27, 2006, a Life Safety Code survey was conducted at Fairwinds - Sandcreek. The facility was found to be providing a safe environment and safe, effective care to residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by August 26, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely.

MARK GRIMES

Supervisor

Fire/Life Safety & Sanitation Program

MG/slc

Enclosure

(X6) DATE

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: A. BUILDING 01 - ENTIRE BUILDING B. WING 13R661 07/27/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 3310 VALENCIA DR **FAIRWINDS - SANDCREEK** IDAHO FALLS, ID 83404 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (X4) ID (EACH DEFICIENCY MUST BE PRECEEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) R9999 Initial Comments R9999 The facility was found to be in substantial compliance with the fire and life safety standards of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on July 27, 2006.. The surveyor conducting the survey was: Mark Grimes, Supervisor Facility Fire and Construction Program Team Leader Health Facility Surveyor **Taylor Barkley** Health Facility Surveyor Debby Ransom **Bureau Chief Facility Standards** Bureau of Facility Standards

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM 6899 6V8I21 If continuation sheet 1 of 1

TITLE

BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888 ASSISTED LIVING Non-Core Issues Punch List

Facility Name	Physical Address	Phone Number
FAIRWINDS SAND CREEK	3310 Valencia Drive	542-6200
Administrator	City	ZIP Code
KEN Madsen	Idaho Falls	83404
Survey Team Leader	Survey Type	Survey Date
MACK GRIMES	Fire Life Satety	1/2406

NON-	CORE ISSUES	
ITEM #	RULE#	DESCRIPTION DATE RESOLVED
1	404.01	A) STORAGE OF Flammable liquips in Boiler Room W6 17-30.06
		B) Storage of materials that Block Access to glectrical Panels Why 30-0
		acceptional controls at Generactor, and Fire Sprinkler RISERIN
		Simulation
	waiting to rear	c) Boilers, pressure vessels and but water heaters annual cretification
	JCO will compile	INSPECTIONS AZE OVER DUE.
	by 10-1-06	P) Smake seperation doors did not fully latch; NEAR: VMB-1-06.
OIM	, .e	Billiago Room
		Hallway South Rooms 101-121
		NEAR ROOM NIZZ
		2) Exit light illumination NOT FUNCTIONAL OR portially 18-1-06
		functional throughout facility
2	405.01, B	Extension CORD, N SALON - NOT Allowed AS PERMENANT WIRING, 5-21-06
3	415.05.	FIRE Alcen System Annual Inspection - Not current Last
		INSPECTION NEV 2004. 11-05.
		RECEIVED .
Response	Required Date	Signature of Facility Representative
		Ken Marken AUG 2 8 2006